NO. 5708 P. 41/60

Fig.1(a)





Fig.1(b)








Fig.2




NO. 5708 P. 43/60

Fig.3



NO. 5708 .P. 44/60

Fig.4



NO. 5708 P. 45/60

Fig.5






Fig.6





Fig.7



NO. 5708 P. 47/60

Fig.8





Fig.9

SPA PLASMA TREATMENT



7/11




Fig.10





Fig.11








Fig.13




9/11

NO. 5708 P. 50/60



PAGE 50/60 * RCVD AT 9/24/2004 5:44:45 AM [Eastern Daylight Time] * SVR:DCNTFAX01/2 * DNIS:6285116 * CSID:81354701911 * DURATION (mm-ss):17-18

NO. 5708 P. 51/60



11/11